

## Specifications

Species: Siberian larch Humidity:

14% +/- 2%.

One side is considered the front side.

Tolerance: in thickness - /+0.5mm, in width - /+1mm, in length - +25/-12mm

Allowable deflection (longitudinal): 0.5-0.8% of the length

For non-front sides, flaws are unlimited, except for: wane (violating geometry), rot, through cracks are not allowed.

Extra/prima faults for the front side:

vices	Variety "EXTRA"	Variety "PRIMA"
1. Knots are healthy intergrown, healthy not intergrown (not falling out), healthy partially fused	Not allowed	Allowed up to 10 mm no more than 1 knot per running meter
3. Healthy knots unfused (falling out)	Not allowed	Not allowed
6. Tears, chips in the area of knots, holes from knots.	Not allowed	Not allowed
7. Cracks.	Not allowed	hairline up to 1mm wide
10. Resin pockets (width over 3mm)	Not allowed	1 maximum pocket per linear
11. Pitching	Not allowed	Not allowed
13. Wormhole	Not allowed	Not allowed
14. Rot	Not allowed	Not allowed
16. Blue	Not allowed	Not allowed
17. Processing	No defects allowed gouges (roughness and a small tear on the edge in the zone knots), pile on the front non-projection surface	Gouging defects are not allowed (roughness and a small tear on the edge in the zone knots), pile on the front non-projection surface
18. Wane	Not allowed	Not allowed

Defects grade AB for the front side:

vices	Grade "A"	Grade "B"
1. Knots healthy intergrown	allowed	allowed
2. Healthy knots, partially fused	allowed	allowed
3. Healthy knots unfused (falling out)	d up to 5 mm 1 pc. per 1 p/m	on plastic are allowed diameter up to 20 mm with outlet per edge 1 pc. per 1 p/m
4. Healthy knots unfused (not falling out)	allowed d up to 15 mm	allowed d up to 50 mm
5. Eyes (black knots)	allowed up to 7 mm	allowed up to 50 mm
6. Tears, chips in the area of knots, holes from knots, knots rotten, rotten and tobacco.	allowed:	allowed up to 20 mm 1 PC. per 1p / m in the number of falling knots (item 3)
	1.on the bottom edge of the groove: no limit;	
	2. On the upper edge of the groove: d up to 5 mm 1 pc. per 1 p/m in quantity falling knots (item 3).	
7. Cracks.	hair 1/2 product length	hair By all length face plate
	8. Core	
9. Roll	allowed if it does not affect assembly	allowed
10. Resin pockets (width over 3mm)	allowed up to 20 mm 2 PC. per 1 p/m	allowed
11. Pitching	allowed	allowed
12. Prorost	allowed up to 48 mm	allowed
13. Wormhole	not allowed	allowed small 3 pcs. for 1 p/m
14. Rot	not allowed	not allowed
15. Coloring	allowed up to 10% of the surface products	allowed
16. Blue	not allowed	light 10% of the total area
17. Processing	slight gouging defects are allowed (roughness and a small tear on the edge in the area knots)	lint is allowed on the front surface of the non-stitch on crest and other gouging defects that do not affect assembly
18. Wane	not allowed	allowed: on the bottom edge of the groove - no restrictions on the ridge - invisible when assembled